Silly is County of Landson	Sanitize	ed Copy Approved for Relea	ase 2010/05/25 : CIA-RD	P89B0056	9R00070018	0071-1
mades of the control	68332	16 NOA 63	SECREC	3 - 3	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	The state of the s
25X1	DIRECTOR					
				PRIORITY		
		OPS 1-7		हिन्द्य (g .	IN99867	
Manufacture (1) A. I.	TOR 3	1159Z 10 NOV 63				A
25X1 · ·			<u>till til til til til til til til til til</u>		om Linum in one of	8479
	1. G-	3238/100005Z/359。				25X1
	2. 32/32/51/09.					
	3. 118/100/15/62.					
	A. 9R 0-20- 6000/227-16-4-3/9L 0-20- 6003/227-16-14-4-3.					
	B. 60/D5/10/150/MINUS BLUE.					
or the water to the characteristic report departments of	C. 3563/3563.					
	D. I-100058Z/II-100132Z/STBY-100312Z/I-100323Z/STBY-					
	100338Z/1-100355Z/II-100433Z/I-100531Z/STBY-100516/OFF-100617Z.					
25X1 25X1	20	11008302.				
	F. 21/48.					
	G.	030071/033634.		25 YEAR RE-REVIEW		
	A. o	80 PER CENT CLEAR/	NONE.	•		
	I o	NONE/SATISFACTORY.				
	4. NO	APPARENT DISCREPAN	CY WITH	FIRST	90 MINUT	ES OPERATION
1 V" 1 TO April	PLATFORM HAD 5 DEG WALLOW-ROLL DUE TO AUTO PILOT.					
A VINCENTIAL CONTINUES	END OF MESSAGE					
process in the		j. eron	na nominara de ambiento ambiento de la compansión de la compansión de la compansión de la compansión de la comp	T. THE RESERVE	2007 (E 1946) 15 100 \$ 2005/2016 2008/2016 (E 1946) 16 10 10 10 10 10 10 10 10 10 10 10 10 10	

S F C R F T
Sanitized Copy Approved for Release 2010/05/25 : CIA-RDP89B00569R000700180071-1